

# MODIFICATION RECOMMENDATION

## FORM MPID 259 – HOUSEKEEPING MODIFICATION TO THE DEFINITIONS SECTION OF THE GLOSSARY (FLEXIBLE OUTAGE).



*RECOMMENDATION TO CER BY EIRGRID OF MODIFICATION TO GRID CODE.*

<b>ABSTRACT / TITLE OF MODIFICATION</b>	<b>MPID 259 – HOUSEKEEPING MODIFICATION TO THE DEFINITIONS SECTION OF THE GLOSSARY (FLEXIBLE OUTAGE).</b>
<b>MODIFICATION NUMBER</b>	MPID 259
<b>RECOMMENDED AT GCRP MEETING NUMBER</b>	39
<b>LIST OF GRID CODE SECTION(S) AFFECTED BY PROPOSED MODIFICATION:</b>	Glossary - Definitions
<b>CURRENT GRID CODE VERSION :</b>	5
<b>MODIFICATION DESCRIPTION Overview</b>  <b>THE REASON FOR THE RECOMMENDED MODIFICATION</b>	<p>EirGrid are proposing a housekeeping modification to the definitions section of the glossary. The alphabetical ordering of the Grid Code term <b>Flexible Outage</b> is incorrect.</p> <p>We propose moving and placing the Grid Code term <b>Flexible Outage</b> after the Grid Code term <b>Fault Ride-Through Time</b>.</p>
<b>History of Progression through GCRPs, Working Group and/or Consultation</b>	<p>Eirgrid presented the modification proposal MPID 259 to the Grid Code Review Panel members at a meeting held at The Spencer Hotel in Dublin on the 11<sup>th</sup> June 2014. No objections were raised by the panel members and the modification was recommended for approval.</p>

<b>Summary Note of any Objections to the Recommended change from GCRP Members or Consultation Responses</b>	No objections were raised.
<b>Outcome of any GCRP Meeting Actions Relating to the Recommended Modification</b>	No objections were raised.
<b>Implication of not implementing the Modification</b>	It is alphabetically incorrect to have the Grid Code term <b>Flexible Outage</b> after the Grid Code term <b>Facility</b> and before the Grid Code term <b>Failure to Follow Notice to Synchronise Instruction</b> .